

青海电力

QINGHAI ELECTRIC POWER

- 本期** □ 一种椭球型混合式永磁转子同步电机优化设计及特性对比分析
- 期视点** □ 高压直流输电系统无功控制策略及建模研究
- 以调控大数据平台为基础的电网数据精益化管理**
- 一起变电站直流系统异常引起事故分析**



ISSN 1006-8198



9 771006 819187

青海省电机工程学会
青海电力科学试验研究院

主办

2018 4
第37卷
总第144期(卷终)
2018年12月

目 次

分析探讨

一种椭球型混合式永磁转子同步电机优化设计及特性对比分析

..... 何 松,于永军,马 涛,李开鑫,司纪凯(1)

高压直流输电系统无功控制策略及建模研究 程 林,任 冲,孙震宇,樊国伟(6)

费控电能表卡表交互系统调制解调器设计研究 梁 捷(10)

以调控大数据平台为基础的电网数据精益化管理 赵金朝,冶莉娟(14)

电网工控安全实验室建设及运行管理探讨 景延嵘(21)

试验研究

基于有限元分析法的 GIS 超声波故障定位技术研究与应用

..... 杜晓东,李秋阳,杨韬辉,马旭东,马永福,蒋 玲,马志青,于鑫龙(25)

某水库高水位运行期间大坝渗流性态分析 逯玉明(31)

某变电站边坡开挖岩土力学特性数值分析 夏森林,星文太,韩广秋(37)

某 750 kV 并联电抗器合闸过程振动特性分析 杨 勇,宋晓童,马 涛,李富荣(41)

事故分析

桥铝二厂 330 kV 远跳保护死区分析及对策 肖力立(45)

一起变电站直流系统异常引起的事故分析 韩晓惠(49)

一起 220 kV GIS 断路器储能回路故障分析与处理

..... 胡义涛,王 锰,袁 露,胡茂亮,马 凯(53)

一起 35 kV 电磁式电压互感器故障仿真与分析

..... 蒋 玲,刘敬之,李占林,苟廷韬,李秋阳,陈 尧,彭 浩(57)

750 kV 变电站 GIS 母线壳体开裂失效分析

..... 刘高飞,张 烁,云 峰,王志惠,何喜梅,陈文强,樊 超(60)

综合管理

浅谈青海电网深度调峰辅助服务市场建设细则及改造思路

..... 赵文强,马润生,宋晓童,周 军(65)

物资电商化采购规范管控研究 赵 勇,罗 峻,张顺成,白莉珍(67)

封面照片 国网青海省电力公司西宁供电公司 提供

CONTENTS

ANALYSIS AND DISCUSSION

Optimizing Design and Characteristic Analysis of a Ellipsoidal Hybrid Permanent Magnet Synchronous Motor	HE Song, YU Yongjun, MA Tao, LI Kaixin, SI Jikai(1)
Research on Reactive Power Control Strategy and Modeling of HVDC Transmission System	CHENG Lin, REN Chong, SUN Zhenyu, FAN Guowei(6)
Design and Research of Modem for Card Meter Interaction System of Fee-Control Electric Energy Meter	LIANG Jie(10)
Lean Management of Grid Data Based on Regulating Big Data Platform	ZHAO Jinchao, YE Lijuan(14)
Discussion on Construction and Operation Management of Power Grid Industrial Control Safety Laboratory	JING Yanrong(21)

TEST AND RESEARCH

GIS Ultrasonic Wave Based on Finite Element Analysis Study and Application of Fault Location Technology	
---	--

DU Xiaodong, LI Qiuyang, YANG Taohui, MA Xudong, MA Yongfu, JIANG Ling, MA Zhiqing, YU Xinlong	(25)
---	------

Seepage Characteristics Analysis of a Reservoir Dam During Operation at High Water Level	LU Yuming(31)
Numerical Analysis of the Rock-soil Mechanics Characteristics of the Slope Excavation Work in a Substation	XIA Senlin, XING Wentai, HAN Guangqiu(37)
Analysis of Vibration Characteristics of a 750 kV Shunt Reactor in the Process of Closing	YANG Yong, SONG Xiaotong, MA Tao, LI Furong(41)

ACCIDENT ANALYSIS

Analysis on the Dead Zone of the 330 kV Remote Trip Protection of the Secondary Qiao-tou Aluminum-Electricity Plant and the Countermeasures	XIAO Lili(45)
The Anomaly Analysis and Suggestion of DC System of Power Plant and Substation	HAN Xiaohui(49)
Analysis and Treatment of a 220kV GIS Breaker Energy Storage Circuit Fault	HU Yitao, WANG Meng, YUAN Lu, HU Maoliang, Ma Kai(53)
Simulation and Analysis on a Fault of 35 kV Electromagnetic Voltage Transformer	JIANG Ling, LIU Jingzhi, LI Zhanlin, GOU Tingtao, LI Qiuyang, CHEN Yao, PENG Jie(57)
Cracking Failure Analysis of GIS Bus Shell in 750 kV Substation	LIU Gaofei, ZHANG Shuo, YUN Feng, WANG Zhihui, HE Ximei, CHEN Wenqiang, FAN Chao(60)

MANAGEMENT

Disscussion on the Detailed Rules for Construction of Auxilliary Service Market for Deep Peak Regulation in Qinghai Power Grid	ZHAO Wenqiang, MA Rungsheng, SONG Xiaotong, ZHOU Jun(65)
Study on the Regulation and Control of the E-commerce Purchase of Materials	ZHAO Yong, LUO Jun, ZHANG Shuncheng, BAI Lizhen(67)



北国之春

邓大勇 摄影

ISSN 1006-8198
CN 63-1041/TM

万方数据

广告经营许可证号：6300005000006 国内定价：10.00元