

地震影响下西南干旱山区泥石流危险性特征与防治对策	陈宁生, 邓明枫, 胡桂胜, 等	1
汶川地震诱发滑坡方向效应研究	许 强, 李为乐	7
地形条件对次生山地灾害易发性分析	韩用顺, 梁 川, 崔 鹏, 等	15
汶川地震后北川干溪沟山地灾害及长期发展趋势初步分析	陈晓清, 崔 鹏, 李 泳, 等	22
彭州市震后地质灾害特征与重建建议	田宏岭, 杨宗信, 王 萌	33
地震后降雨激发区域地质灾害危险性预测	杨宗信, 乔建平, 田宏岭, 等	38
基于子流域的地震诱发崩塌敏感性评价	张建强, 崔 鹏, 向灵芝, 等	43
神经网络和集成学习在地质灾害危险度区划中的应用研究	赵向辉, 付忠良, 谢会云, 等	50
不同形态开挖损伤斜坡的地震荷载响应分析	阿发友, 孔纪名, 倪振强, 等	56
以重建生产力为目标编制灾后重建规划——以龙溪乡羌人谷东门寨灾后重建规划为例	曹雪梅, 刘 瑛	63
节理岩质边坡破坏过程的 PFC2D 数值模拟分析	李新坡, 何思明	70
汶川地震堰塞湖地区水安全综合评价	王绍玉, 唐桂娟	76
对汶川地震灾区文化遗产建筑震害与保护的几点思考	潘 毅, 赵世春, 余志祥, 等	82
地震载荷作用下钢框架梁柱节点的低周疲劳损伤累积分析方法及探讨	王志宇, 王清远, 田仁慧, 等	86
地震作用下桩锚组合结构加固边坡稳定性分析	罗 澜, 何思明, 欧阳朝军, 等	93
宝珠寺重力坝地震前后渗流原观特性对比分析	裴 亮, 吴震宇, 陈建康	100
汶川地震堰塞湖安全实例分析	张 靖, 黄 尔	107
预制混凝土框架中节点抗震性能的试验研究	蔡建国, 赵耀宗, 朱洪进, 等	113
再生混凝土轴心受拉性能试验与格构数值模拟	刘 琼, 肖建庄, 李文贵	119
崩滑体动力学机理分析及全过程速度计算——以四川省汉源县“8·6”大型崩塌滑坡为例	周小军, 崔 鹏, 葛永刚, 等	125
现代木结构在汶川地震灾后重建中的应用及国产木剪力墙抗震性能研究	黄 浩, 何敦娟, 周楠楠, 等	132
汶川地震震后都汶公路的恢复与重建	裴来政, 刘应辉, 庄建琦	140
基于 OpenSEES 的预应力装配双肢墙低周往复试验数值分析	蔡小宁, 孟少平, 孙巍巍, 等	147
关于“山洪防治及防汛预警系统建设”的几点建议	黄 华, 彭 盈, 谢新生, 等	154
毛尔盖水电站提前下闸蓄水过程及电量影响分析	冯 宇	161
模拟地震对新浇注混凝土钢筋握裹强度的影响	徐明强, 李国华, 魏建东, 等	166
不同再生骨料取代率的再生混凝土性能试验研究	石宵爽, 王清远, 邱慈长, 等	170
钢筋混凝土框架结构中板式楼梯梯段板抗震分析及其设计对策	何世龙, 宋吉荣	177

[期刊基本参数] CN51-1596/T * 1957 * b * A4 * 184 * zh * P * ¥ 15.00 * 1000 * 28 * 2010-09

责任编辑:赵 靖

英文校订:江成发

出版日期 · 2010 年 09 月 30 日 ·

JOURNAL OF SICHUAN UNIVERSITY
(ENGINEERING SCIENCE EDITION) (Bimonthly)
Vol. 42 Supp. 1 2010

□Contents□

Risk Characteristics and Prevention Strategy of Debris Flow Under the Seismic Influence in Mountainous Arid Area, Southwest China	CHEN Ning-sheng, DENG Ming-feng, HU Gui-sheng, et al	1
Study on the Direction Effects of Landslides Triggered by Wenchuan Earthquake	XU Qiang, LI Wei-le	7
Susceptibility of Mountain Hazards Triggered by Wenchuan Earthquake to Topographic Factors ...	HAN Yong-shun, LIANG Chuan, CUI Peng, et al	15
Mountain Hazard Induced by Wenchuan Earthquake and Its Long-term Development Trends of Ganxi Gully, Beichuan	CHEN Xiao-qing, CUI Peng, LI Yong, et al	22
Geological Disaster Characteristics and Reconstruction Suggestions for Pengzhou After "5 · 12" Earthquake	TIAN Hong-ling, YANG Zong-ji, WANG Meng	33
Study on Rainfall-induced Regional Geohazards Prediction Following Wenchuan Earthquake	YANG Zong-ji, QIAO Jian-ping, TIAN Hong-ling, et al	38
Susceptibility Assessment of Landslides Induced by Earthquake Based on Sub-basin	ZHANG Jian-qiang, CUI Peng, XIANG Ling-zhi, et al	43
Application Research of Ensemble Learning and Neural Network on Geological Hazard Fatalness Zoning	ZHAO Xiang-hui, FU Zhong-liang, XIE Hui-yun, et al	50
Analysis of Seismic Loading Response for Different Excavation Damaged Slope	A Fa-you, KONG Ji-ming, NI Zhen-qiang, et al	56
Productivity as the Goal to Rebuild the Preparation of Reconstruction Plans —Take the Reconstruction Planning of Longxi-Dongmen Village as a Specific Example	CAO Xue-mei, LIU Kun	63
Numerical Analysis of the Failure of Heavily Jointed Rock Slopes Using PFC2D	LI Xin-po, HE Si-ming	70
Water Safety Evaluation in the Regions of Wenchuan Earthquake Landslide Lake	WANG Shao-yu, TANG Gui-juan	76
Analysis and Investigation on the Seismic Damage and Protection of Cultural Heritage Architecture in Wenchuan Earthquake	PAN Yi, ZHAO Shi-chun, YU Zhi-xiang, et al	82
Discussion on Low-cycle Damage Accumulation Assessment Approaches of Steel Beam-to-column Joint Under Seismic Loading	WANG Zhi-yu, WANG Qing-yuan, TIAN Ren-hui, et al	86
Stability Analysis of Pile and Anchor Composite Structure Reinforced Slope Under the Earthquake Loading	LUO Yu, HE Si-ming, OUYANG Chao-jun, et al	93
Comparative Analysis of Prototype Observation Characteristics on Baozhusi Gravity Dam Before and After Earthquake	PEI Liang, WU Zhen-yu, CHEN Jian-kang	100
Safety Analysis of Dammed Lakes in Wenchuan Earthquake	ZHANG Jing, HUANG Er	107
Study on Seismic Behavior of Interior Joints of Precast Concrete Frames	CAI Jian-guo, ZHAO Yao-zong, ZHU Hong-jin, et al	113
Axial Tensile Test and Lattice Model Simulation on Recycled Concrete	JIU Qiong, XIAO Jian-zhuang, LI Wen-gui	119
Dynamic Mechanism Analysis and Speed Calculation During Full Course Movements of Landslide; Taking Landslide Occurred at Hanyuan County on August 6th, 2009 as a Sample	ZHOU Xiao-jun, CUI Peng, GE Yong-gang, et al	125
Application of Modern Timber Structure in Post-disaster Reconstruction of Wenchuan Earthquake and the Seismic Performance of Wood Shear Walls Fabricated Using Chinese Wood	HUANG Hao, HE Min-juan, ZHOU Nan-nan, et al	132
Restoration and Reconstruction of Du-Wen Highway After the Wenchuan Earthquake	PEI Lai-zheng, LIU Ying-hui, ZHUANG Jian-qi	140
Numerical Analysis for Low-cyclic Loading Test of Post-tensioned Coupled Wall Based on OpenSEES	CAI Xiao-ning, MENG Shao-ping, SUN Wei-wei, et al	147
Suggestions of "the System Construction of Mountain Flood Prevention and Preview Warning" ...	HUANG Hua, PENG Ying, XIE Xin-sheng, et al	154
Analysis on the Process of Impounding Water and Power Generation Quantity About an Ahead of Schedule Impounding Scheme of Mao'ergai Hydropower Station	FENG Yu	161
Effect on the Bond Strength of Steel Bars of Fresh Concrete After the Occurrence of an Simulated Earthquake	XU Ming-qiang, LI Gu-hua, WEI Jian-dong, et al	166
Experimental Study on the Properties of Recycled Aggregate Concrete with Different Replacement Ratios from Earthquake-stricken Area	SHI Xiao-shuang, WANG Qing-yuan, QIU Ci-chang, et al	170
The Countermeasure of Seismic Analysis and Design for the Stair Bench Slab of Plate Stairs in Reinforced Concrete Framework Structure Buildings ...	HE Shi-long, SONG Ji-rong	177

▷ Published on Sept. 30, 2010 ◁